



Permit Status:
Permit Number:
Permite Description:
Total Outstanding Inspections - 4

Last Inspection Date	Description	Inspector	Results	Comments
08/08/2022	COT - FCOD - Fire Re-inspection		Completed	<p>04/8/2022 SWS- I re-inspected the building being used as a school. Some 2A10BC fire extinguishers have been installed near exits. Around a dozen smoke detectors have been installed in some of the classrooms and corridors.</p> <p>Paper, non luminous, non powered exit signs have been installed, Mr Aguirre has been informed that these signs are not acceptable.</p> <p>On being allowed to inspect some previously unseen parts of the building, a small classroom was discovered on the second floor.</p> <p>A large auditorium was discovered, being approximately 10,000 square feet, Mr Aguirre stated that they can have 400 people in there.</p> <p>This room has emergency lighting, but no fire alarm, sprinklers, exit signs or extinguishers. It has stage and organ. The stage curtain does not appear to be fire rated.</p> <p>There are two sets of double doors as the main entrance, the other side of the room has three smaller exits, sufficient for this occupancy.</p> <p>I told Mr Aguirre that the three smaller exits require illuminated exit signs and at least two 2A10BC extinguishers in the room.</p> <p>Looking through Tucson Pro, I can find no information on this building which was allegedly constructed in 1992.</p> <p>08/08/22- SWS - I contacted DPSD, spoke with Yaritza Leon, she found older information on this premises including the Certificate of Occupancy. She is digitizing it and will send it to me hopefully by the end of this week. Speaking to Captain Janton, we have established that this building will certainly require a fire alarm system for A3 and E occupancies. We will determine more once the information comes from DPSD.</p>
07/20/2022	COT - FOPR - Fire General Inspection		Completed	<p>SWS- 07/20/22- Tomasz Piotrowski and I visited this premises to discuss if the second building is being used as a school.</p> <p>The main building (sanctuary) has a sprinkler and fire alarm system, the second building has only emergency lights.</p> <p>We were unable to reach an agreement on the occupancy classification of the second building. Raymondo Aguirre was told to apply to the city of Tucson DPSD</p>

department for a determination. The COO for the sanctuary is A3(church) we could not find a COO for the second building, it is believed to date back to 1992. I required the installation of smoke alarms, extinguishers and exit signs as a temporary minimum. (see report).

06/28/2022	COT - Fire - Complaint	Completed	SWS 6/28/2022- Tony Smith received a complaint email from Tim Kraus. Tim claimed that the Golden Dawn Tabernacle was operating an unauthorised school in their fellowship hall. Tony and I met with Ray Aguirre at the premises and the claim appears correct. We are finding the right contact at the State to start the process of getting the school appropriately licensed. Ray Aguirre 520-437-3994
11/25/2014	COT - FCON - Underground Pressure	Completed	Approved - CB 1. Per General Contractor depth of final grade will be 30 inches minimum.
